



Release Notes

v3.1000 for Sage 925VST/325EV Responder

This document describes a new software release (v3.1000) for the 925VST Handheld VoIP Service Tester and 325EV Packet Voice Responder. This software supersedes Version 3.0001 and is available now.

Corrections

1. Corrects a 'memory leak' defect that caused 4-wire SMOS tests to crash after sustained use.