



## **Release Notes**

### **v3.5012 for Sage 925VST/325EV Responder**

This document describes a new software release (v3.5012) for the 925VST Handheld VoIP Service Tester and 325EV Packet Voice Responder. This software supersedes Version 3.5008 and is available now.

#### **Corrections**

1. Corrects a defect in the MoIP (Modem Over IP) test that could occasionally cause greatly inflated packet loss reports.
2. Setting the Echo Generator Responder duration to other than default results in unpredictable durations. However, choosing "Default" reliably sets the timeout period to the default 300 seconds (5 minutes).

This defect has been partially corrected: Now, you can set the timeout up to 59,940 seconds (999 minutes). BUT, you have to power cycle the unit before the setting takes effect.

#### **Known Problems**

1. See item #2, above.